22 **December** 1965

	Subject: ECP GR-35, Contract LP-2264	
	Dear Chuck,	
STAT	Item one of this ECP is disapproved by the SPO. We have no evidence that the present control design for the multiplex switch contributes to excessive failures of these switches. There is one advantage, however, to the present design in that the multiplex switch operation can be checked	STA ⁻
SIAI	without having to turn on the	STA
:	Item two of this change, re-routing of J-Box wiring is required and approved. We understand that Nat considers this a contractor responsible change. Accordingly, Nat should be requested to submit a revised ECP to cover this no cost portion of the change, unless you think this unnecessary.	
	Regards	
STATINTL	Copy:	STATINTL

Approved For Release 2002/10/25 :	CIA-RDP72B00464F	AKP-I-4980 8 December 19	// //	668 KITL(2)
				1

STATINTL

TO:

ENCLOSURES:

ECP GR-35, 7 copies 11-12-65

N-R Agreement, Serial G-83 of 10-7-65 N-R Agreement, Serial G-158 of 12-6-65 ADP Discrepancy Report No. 87, 10-4-65

Dear Phil:

Submitted for your approval is ECP GR-35, dated 11-12-65. We are proceeding with this change prior to change proposal approval. The Production units will be changed as indicated by GR-35.

The eight (8) Prototype units will be retrofitted by GR technicians. The change to be made to the prototype units include a new relay bracket P/N 531A620-099-1, which will be used in a 531A620-028-101 Relay Assembly that can be mounted into the J-Box on existing mounting hardware.

The total cost for the eight (8) prototype units will be \$1603.90 which includes \$1,178.56 engineering costs. Kit costs will be \$53.16 per unit.

No costs have been included for providing that portion of the change associated with the Man 28V DC signal to the Synchronizer in the Programmed mode.

NAT NAT

N/mj encls.

STATINTL

cc:

partially approved 22 Dec.

Approved For Release 2002/10/25 : CIA-RDP72B00464R000400070067-2

2 (4 6 2) (4) mgr

Approved For Release 2002/10/25 : CIA-RDP72B00464 R000400070067-2 ENGINEERING STUDY **GA-531 GR-** 35 X. CHANGE PROPOSAL DATE 11-12-65 AFFECTS: GA531A STAT NAME OF MAJOR COMPONENT PART OR LOWEST SUBASSEMBLY PART NO. System Junction Box MODEL OR TYPE System Junction Box 531A620-001-105 No P/N Change Improve control of multiplex switch and provide Man-Prog Mode. compatability for the Synchronizer. NATURE OF PROPOSAL: 1. Install 6K12 relay, connector and wiring, and reroute wiring to permit operation of multiplex switch. 2. Reroute wiring in J-Box to provide circuit to Synchronizer for "Man 28V DC 3. A Mod. No. will be assigned with the incorporation of this change. REASON FOR PROPOSAL:
1. Conserve the operating life of the slave multiplex switch and to permit slave multiplex switch only when the is switched on. Ref: STAT ADP Eng. Discrepancy Report No. 87. 2. Provide a "Man 28V DC" signal to the Synchronizer Unit in the Programmed Mode as well as the present Manual Mode. REF: N/R No. G-83. ESTIMATED COST AND TIME INVOLVED: ES ADDITIONAL FUNDING REQUIRED: ESTIMATED COST FOR KITS OR PARTS: \$33.23 CP ADDITIONAL FUNDING REQUIRED: \$4547.77 (includes \$3,783.34 Engineering) Units S/N 6051-9 thru -20 will be retrofitted. ITEMS AFFECTED BY PROPOSAL: Production units S/N 6051 and Subs in line. MISSION INTER-WEIGHT OR TOOLS AND MAINTE-MAINTE-PERFORM-OPERATING SAFETY EFFEC-SERVICE CHANGE-SUPPORT FLIGHT NANCE NANCE AND BALANCE ANCE PROCEDURE TIVENESS ABILITY LIFE EQUIPMENT MANUAL PROCEDURE MANUAL \Box Κ̈́ 鬥 ESTIMATED MAN HOURS REQUIRED TO ACCOMPLISH CHANGE IN FIELD: 8 hours per unit rework time. SOURCE OF PARTS FOR KIT: GR 6 AVAILABILITY _ - WEEKS AFTER APPROVAL STATINTE STATES AFFECTED: Spares to be changed to latest configuration. PPB to be changed by change notice to PSO. STATINTL IN

Approved For Release 2002/10/25 : CIA-RDP72B00464R0004000700양연호